

General Environmental Incident Summary

Incident: 3444 **Date/Time Notice:** 9/2/2014 1400 **DEM Incident No:**
Responsible Party: InCorr Chemical
Date Incident: 9/1/2014 **Time Incident:** 1730 **Duration:** 2 minutes
County: Williams **Twp:** 155 **Rng:** 97 **Sec:** 5 **Qtr:** NE NE NW
Lat: 48.28363 **Long:** -103.18540 **Method:** Address matching
Location Description: Well Name: Columbia Federal 6-5H 7-5H1.
From Williston head N on Hwy 2 follow to 119th ave (CR15) take a right.
Continue south on 119th 4 miles to 60th street take a left on 60th street
follow for 3.4 miles to location on the right.
Submitted By: Kent Donner **Affiliation:** Vice President
Address: 3218 111 H Avenue SW
Suite G
City: Dickinson **State:** ND **Zip:** 58601

Received By:

Contact Person: Kent Donner
3218 111 H Avenue SW
Suite G
Dickinson, ND 58601

Distance Nearest Occupied Building: 1.2 Miles **Release Contained:** No

Type of Incident: Tank Overflow

Description of Released Contaminant: Shrieve Chemical Company - BIO-EXP 13-59. Instant Cross Linker.

Volume Spilled: 40.00 gallons **Ag Related:** No

EPA Extremely Hazardous Substance: No **Reported to NRC:** Unknown

Cause of Incident:

Tank Overflow

Risk Evaluation:

None

of Fatalities: 0 **# of Injuries:** 0 **Affected Medium:** 03 - soil

Potential Environmental Impacts:

None. Only contaminated soil. No risk to water bodies or ground water.

Action Taken or Planned:

Spill was largely contained in spill containment. Some liquids splashed onto the ground. All waste has been recovered and returned to company's warehouse. Liquids were recovered in plastic totes. Contaminated soil was recovered into 55 gallon drums.

Wastes Disposal Location: To be determined.

Agencies Involved:

Updates

Date: 9/2/2014 **Status:** Reviewed; Followup Required **Author:** Roberts, Kris

Updated Volume:

Notes:

Tank overflow. Follow-up necessary.

Date: 9/2/2014 **Status:** Reviewed; Followup Required **Author:** Martin, Russell

Updated Volume:

Notes:

Based on report, release due to tank overflow was not entirely contained within spill containment. Followup is necessary.

Date: 9/3/2014 **Status:** Inspected **Author:** Washek, Sandi

Updated Volume: 40.00 gallons

Notes:

Arrived on site. Weather was overcast and wind out of the NE at 5-10 mph. Safety officer and company consultant showed both NDDoH inspectors the area of impact. The soil had been cleaned up, and a catch basin was installed under the tank. No material left the well pad. No additional followup needed for site.